

# Icelock 850 Hybrid Coding Guidance

## Suggested Coding

- Icelock 850 Hybrid
  - L5671
- Iceross Seal-In X Locking TF coding options:
  - L5679 & L7700; OR
  - L5673



## Coding Guidance

Suggested coding for Icelock 850 Hybrid with Iceross Seal-In X Locking TF: **L5671** and **L5673**<sup>1</sup>

## Additional Suspension Coding Options

1. Suction suspension (L5652) can be used ONLY IF a suction valve is modified into the socket itself (this is not a feature built into L5671).
2. Vacuum suspension (L5781) can be used ONLY IF a vacuum pump suspension is used.

*\*\*This guidance is based on Medicare policy. For commercial and state plans, review the applicable medical policy for appropriate coding guidelines.*

The responsibility for accurate coding lies solely with the provider treating the patient. Össur assumes no responsibility or liability for the provider's coding decision. Össur's coding suggestions rest on its best judgment and are subject to revision based on additional information or changes in the alpha-numeric system.

---

<sup>1</sup>The cushion liner (L5679) description states that it "is NOT for use with locking mechanism," and the Policy Article states that the moveable gasket/seal (L7700) CANNOT be billed with mechanical socket suspensions such as pin-lock systems. Therefore, L5679 and L7700 cannot not be billed with L5671.