


How to measure your knee for a GenuTrain® S Pro knee support.



Measure the circum-
ference of your leg at
two points:

**4 3/4" below the knee
and 5 1/2" above the
middle of the knee.**

Size	A Circumference (inch)	B Circumference (inch)
1	11-12 1/4	15-16 1/4
2	12 1/4-13 1/2	16 1/4-17 1/4
3	13 1/2-14 1/2	17 1/4-18 1/2
4	14 1/2-15 3/4	18 1/2-19 3/4
5	15 3/4-17	19 3/4-20 3/4
6	17-18	20 3/4-22
7	18-19 1/4	22-23 1/4