


How to measure your knee for a GenuTrain® P3 knee support.



Measure the circum-
ference of your leg
at two points:

**6" below the knee and
6 3/4" above the middle
of the knee.**

Size	A Circumference (inch)	B Circumference (inch)
1	11-12 1/4	15 1/4-16 1/2
2	12 1/4-13 1/2	16 1/2-17 3/4
3	13 1/2-14 1/2	17 3/4-19
4	14 1/2-15 3/4	19-20
5	15 3/4-17	20-21 1/4
6	17-18	21 1/4-22 1/2