


How to measure your knee for a **GenuTrain® S** knee support.



Measure the circumference of your leg at two points:

**4³/₄" below the knee
and 5¹/₂" above the
middle of the knee.**

Size	A	B
	Circumference (inch)	Circumference (inch)
1	11-12 ¹ / ₄	15-16 ¹ / ₄
2	12 ¹ / ₄ -13 ¹ / ₂	16 ¹ / ₄ -17 ¹ / ₄
3	13 ¹ / ₂ -14 ¹ / ₂	17 ¹ / ₄ -18 ¹ / ₂
4	14 ¹ / ₂ -15 ³ / ₄	18 ¹ / ₂ -19 ³ / ₄
5	15 ³ / ₄ -17	19 ³ / ₄ -20 ³ / ₄
6	17-18	20 ³ / ₄ -22
7	18-19 ¹ / ₄	22-23 ¹ / ₄