


How to measure your knee for a
SecuTec® Genu knee brace.



Measure the circum-
ference of your leg at
two points:

**6" below the knee
and 6¾" above the
middle of the knee.**

Size	①	②
	Circumference (inch)	Circumference (inch)
1	11-12 ³ / ₅	15-16 ⁵ / ₉
2	12 1 ¹ / ₅ -13 ⁴ / ₅	16 ¹ / ₇ -17 ³ / ₄
3	13 2 ² / ₅ -15	17 ¹ / ₃ -19 ¹ / ₃
4	14 1 ¹ / ₆ -15 ³ / ₄	19-20 ⁷ / ₈
5	15 3 ³ / ₈ -17	20-22 ⁴ / ₉
6	16 1 ¹ / ₂ -18 ¹ / ₈	21 ¹ / ₇ -22 ² / ₃