

STOCKING DONNERS	REGULAR	TALL	LARGE
Donning Zone Height =	9"	9"	10"
Donning Zone Width =	4"	4"	6"
Arm Height =	13"	18"	18"
Arm Depth =	3.5"	4"	4"

